

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080122-8

No. 11040

RECEIVED FROM

DATE REC'D. 1-26-57
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.	REMARKS					
6	322	000000	27019	0	0	00	00	03								
DRAWING NO. AND DESCRIPTION																
732797 PLATE ALUMINUM																
SHIP MEMO 85873																
<table border="1"> <thead> <tr> <th colspan="2">QUANTITY</th> </tr> <tr> <th>ACCEPTED</th> <th>REJECTED</th> </tr> </thead> <tbody> <tr> <td>6</td> <td>✓</td> </tr> </tbody> </table>											QUANTITY		ACCEPTED	REJECTED	6	✓
QUANTITY																
ACCEPTED	REJECTED															
6	✓															

RECEIVED BY
HMC 1069

INSPECTED BY

Data DATE 1/29/57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2741 E. COLORADO ST., PASADENA, CALIF.

No. 11042

RECEIVED FROM

DATE REC'D. 1-26-57
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.	REMARKS					
1	322	000000	27036	0	0	00	00									
DRAWING NO. AND DESCRIPTION																
732676 FOR ASS'Y																
SHIP MEMO 85901																
<table border="1"> <thead> <tr> <th colspan="2">QUANTITY</th> </tr> <tr> <th>ACCEPTED</th> <th>REJECTED</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>✓</td> </tr> </tbody> </table>											QUANTITY		ACCEPTED	REJECTED	1	✓
QUANTITY																
ACCEPTED	REJECTED															
1	✓															

RECEIVED BY
HMC 1069

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080122-8